# Weathertzerfon Assistance Program

# Work Order Bid (ID)

# **WORK ORDER INFORMATION**

Work Order Name: WO/90009MD2647/2

Work Order Type: Weatherization

Audit Name: 90009MD2647Audit

# **CLIENT INFORMATION**

Client ID: 90009MD2647

## <u>AGENCY INFORMATION</u>

Agency: Metropolitan Development and Housing Agency Agency Phone: (615) 252-8500

Address: 701 South Sixth Street Fax: (615) 252-8533

Nashville, TN 37206 Email Address:

Company Name & License Number:	
Contractor's Signature:	

### **COMMENT**

Audit performed on 3/26/12

Lead paint may be present Historical Review

Auditor: Randy Radford (615) 335-7428

(010) 333-7420

serviceworks@comcast.net

# Measures

Client ID: 90009MD2647

#### Inspected Measure 1 Seal Ducts **Components Comment** Duct Sealing 1) Seal wood frame to sheet metal where gaps exist in return plenum. 2) Cut 1/2" plywood to fit (approx. 3.25" x 8") and seal around existing floor planks at the Living Room register with clear caulk. **Estimated** Actual # Material / Labor **Description / Comment Units Unit Cost** Total **Unit Cost** Qty Qty **Total** Labor 10 Miscellaneous Su Duct Sealing Each Other Detail Sub Total: Measure Sub Total: Field Notes:

#### Measure 2 Infiltration Redctn

#### **Components**

# Inspected

#### **Comment** Infiltration Measures

- 1) Air seal plumbing penetrations under kitchen sink with caulk
- 2) DR1. Remove existing W/S and replace with new W/S. Attach new W/S and D/S metal with screws.
- 3) DR2. Install new W/S and D/S. Attach new W/S and D/S metal with screws.
- 4) Install chimney balloon in fireplace in front right Bedroom
- 5) Reglaze windows: WD2, WD5 (x2 windows), WD6, WD7. Remove any loose glazing and replace with new.
- 6) Install 1/2" drywall to cover hole in drywall below plumbing box for washing machine in utility room. Air seal with clear caulk.
- 7) Replace damaged fascia on south side wall (the wall with the crawl space access to the main section of the house)(WL7). Replace with a 1x8 fascia board, approx. 24' long, where fascia is damaged. Paint with white exterior paint.
- 8) Replace 1/2" x 3" soffit boards, approx. 10', where damaged or missing on same south wall as damaged fascia. (WL7)
- 9) Replace 9 pieces of 1x5 wood siding approx. 6.5' long on back of house to the left of back door. Siding is falling off of house and is a major air infiltration. (WL5) Cut to fit. Paint with white exterior paint.
- 10) Replace 1 piece of 1x5 wood siding approx. 34" long on back of house to the right of back door, under WD5. (WL5) Cut to fit. Paint with white exterior paint.
- 11) Replace 19 pieces of 1x5 wood siding approx. 9.5' long on south side of house (WL6). Cut to fit. Paint with white exterior paint.
- 12) Replace 6 pieces of 1x5 wood siding approx. 5' long on south side of house (WL6). Cut to fit. Paint with white exterior paint.

				Estimated			Actual		
#	Material / Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
	Labor								
10	Miscellaneous Su	Infiltration Reduction	Each	1					
C	Other Detail								
				Measur	e Sub Total:			Sub Total:	
	Field Notes:								

access p -Use an	sulation at least 2 inches panel. Don't install insula R-8 or higher water-heat vrap" insulation are acce	tion below ter blanke	the but t for the	irner access e unit. Both	panel.			
Natural (	Gas, 40 gal							
				Estimated	<u> </u>	-	Actual	
Material / Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
Hot Water Equipm	DHW Tank Insulation	Each	1					
Labor	DHW Tank Insulation	Each	1					
Other Detail						1		
						] []		
			Measur	e Sub Total:		]	Sub Total:	
<b>Comment</b> -Insulate -Use pip	I Pipe Insulation the the first 6 feet of hot an			Componen	ts			Inspecte
	e wrap with a R-value of the same thickness as	at least 2	er pipe	r elbows, un	ater heat ions and			Inspecte
	the same thickness as	at least 2 pipe.	er pipe . Covei	e from the war elbows, un	ater heat ions and	other	Actual	
	the same thickness as  Description / Comment	at least 2 pipe. <i>Unit</i> s	er pipe . Cover	e from the war	ater heat ions and			Total
	the same thickness as	at least 2 pipe.	er pipe . Covei	e from the war elbows, un	ater heat ions and	other	Actual	
Insulation	the same thickness as  Description / Comment	at least 2 pipe. <i>Unit</i> s	er pipe . Cover	e from the war elbows, un	ater heat ions and	other	Actual	
Insulation Labor	Description / Comment  DHW Pipe Insulation	at least 2 pipe. <i>Units</i> Each	er pipe . Cover . Cover . Qty	e from the war elbows, un	ater heat ions and	other	Actual	Total
Insulation Labor	Description / Comment  DHW Pipe Insulation	at least 2 pipe. <i>Units</i> Each	er pipe . Cover . Cover . Qty	e from the war elbows, un	ater heat ions and	other	Actual	
Insulation  Labor	Description / Comment  DHW Pipe Insulation	at least 2 pipe. <i>Units</i> Each	er pipe . Cover . Cover . Qty	e from the war elbows, un	ater heat ions and	other	Actual	
Insulation  Labor	Description / Comment  DHW Pipe Insulation	at least 2 pipe.  Units Each Each	Qty 1	e from the war elbows, un	ater heat ions and	Qty	Actual	
# Material / Labor Insulation Labor Other Detail Field Notes:	Description / Comment  DHW Pipe Insulation	at least 2 pipe.  Units Each Each	Qty 1	Estimated Unit Cost	ater heat ions and	Qty	Actual Unit Cost	
Insulation  Labor  Other Detail	Description / Comment  DHW Pipe Insulation	at least 2 pipe.  Units Each Each	Qty 1	Estimated Unit Cost	ater heat ions and	Qty	Actual Unit Cost	
Insulation Labor  Other Detail	Description / Comment  DHW Pipe Insulation	at least 2 pipe.  Units Each Each	Qty 1	Estimated Unit Cost	ater heat ions and	Qty	Actual Unit Cost	

	Measure 5 Stor	rm Windows			Componen	ts WD7			Inspected
C	<b>Comment</b> WD7: R	Replace broken storm gla	iss pane o	n windo	w WD7 (ap	prox. 42	x 30)		
				Estimated					
#	Material / Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
1	Windows	Storm Window	SqFt	19.03					
2	Labor	Storm Window	SqFt	19.03					
3	Other	Storm Window	Each Window	1					
(	Other Detail								
				Measure	e Sub Total:		] ;	Sub Total:	
	Field Notes:								

N/	_			D 40
Measure	6	Floor	ıns.	R-19

**Components** Crawl1

Inspected

**Comment** Floor Joist Size: 8

Client ID: 90009MD2647

NOTE: Crawl space has some R-11 fiberglass batts insulation installed, but it is completely useless and is falling down almost everywhere. Remove all the crawl space insulation and replace with new R-19 insulation.

NOTE: Crawl is filled with debris and personal items. Take approx. 2 hours to remove debris and personal items before installing insulation and put back after work is completed.

					Estimated	1	Actual		
#	Material / Labor	Description / Comment	Units	Qty	<b>Unit Cost</b>	Total	Qty	<b>Unit Cost</b>	Total
1	Insulation	Floor Insulation - Fiberglass Faced Batt - R-19	SqFt	824					
2	Labor	Floor Insulation - Fiberglass Faced Batt - R-19	SqFt	824					
3	Miscellaneous Su	Added Misc Cost	Each	1					
C	Other Detail								
				Measur	e Sub Total:		] ,	Sub Total:	
	Field Notes:								

Measure 7	Wall	Insulation			Component	ts WL1,\	WL2,W	L7	Inspected
wa if i ap	all insul insulati ppearar	.2, WL7: Exterior wall tation according to the ng from interior. Holes ace as close to the origing from the interior.	Southeast drilled for i	Field G nsulatio	uide. Get ov on must be r	vner's pe eturned t	rmissio to an		
					Estimated			Actual	
# Material / La	abor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
1 Insulation		Wall Insulation - Cellulose, Blown - 2x4 Filled	SqFt	699.2					
2 Labor		Wall Insulation - Cellulose, Blown - 2x4 Filled	SqFt	699.2					
Other Detail							_		_
				Measur	e Sub Total:		] .	Sub Total:	
Field Notes:	,								

Client ID: 90009MD2647

	_		_	
Measure	8	Attic	Ins.	R-30

**Components** A1

Inspected

**Comment** Existing insulation: 6" of Rockwool INSTALL: 6" of Blown Cellulose

INSTALL. O OI BIOWIT Cellulose

Note: Install dams, baffles to best practices.

REPLACE attic access door: Frame up and install attic access door. An attic access door is installed as a complete unit. A door is inclusive of foam seal, trim, paint(1st quality semigloss color to be chosen by homeowner, caulk, staple R-30 Batt insulation to top of attic access. Refer to Appendix A-Standards for Weatherization Materials and Southeast Field Guide.

			Estimated			Actual		
# Material / Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
1 Insulation	Attic Insulation - Cellulose, Blown - R-30	SqFt	824					
2 Labor	Attic Insulation - Cellulose, Blown - R-30	SqFt	824					
3 Miscellaneous Su	Added Misc Cost	Each	1					
Other Detail								
			Measur	e Sub Total:			Sub Total:	
Field Notes:								

		Monitor is Needed			Componen	ts		,	Inspected
C	comment				Estimated	1		Actual	
#	Material / Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
1	Health and Safety	CO monitor	Each	1					
2	Labor	Labor	Each	1					
(	Other Detail								
				Measur	e Sub Total:			Sub Total:	
	Measure 10 Pres	sureRelief Piping Need	led		Componen				Inspected
C	comment				Estimated	1	04:	Actual	
<b>C</b>	Comment  Material / Labor	SureRelief Piping Need  Description / Comment  Pressure relief piping	ded  Units  Each	<b>Qty</b> 1	•		Qty		Inspected
<b>C</b> #	Comment  Material / Labor	Description / Comment	Units	Qty	Estimated	1	Qty	Actual	
<b>C</b> # 1	Comment  Material / Labor  Health and Safety	Description / Comment Pressure relief piping	<i>Units</i> Each	<b>Qty</b> 1	Estimated	1	Qty	Actual	
<b>C</b> # 1	Comment  Material / Labor  Health and Safety  Labor	Description / Comment Pressure relief piping	<i>Units</i> Each	<b>Qty</b> 1	Estimated	1	Qty	Actual	
<b>C</b> # 1	Comment  Material / Labor  Health and Safety  Labor	Description / Comment Pressure relief piping	<i>Units</i> Each	<b>Qty</b> 1	Estimated	1	Qty	Actual	
<b>c</b> # 1	Comment  Material / Labor  Health and Safety  Labor	Description / Comment Pressure relief piping	Units Each Each	<b>Qty</b> 1 1	Estimated	1		Actual	

Measure 11	Repla	ace Return Filter (20x	25x1)		Componen	ts		ı	Inspected
Comment Ind	clude 5	filters to leave with cli	ent						
					Estimated	<u> </u>		Actual	
# Material / Lal	bor	Description / Comment	Units	Qty	<b>Unit Cost</b>	Total	Qty	Unit Cost	Total
Labor				1					
Heating Equ	ıipmen	Replace Return Filter		1					
Other Detail									
				Measur	e Sub Total:			Sub Total:	
Field Notes:									
<b>Comment</b> Wa	Heate ater He rrently	eater Exhaust Pipe: Repulled away from the v	esecure gas	exhau	• •	ater heat		1	Inspected
ne	aiin an	d safety reasons.			Estimated	ı		Actual	
# Material / Lal	bor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
1 Health and S	Safety	Equipment	Each	1					
2 Labor		Labor	Hour	1					
Other Detail									
Other Detail									
							]		
				Measur	e Sub Total:			Sub Total:	

Measure 13 Smoke Detector is Needed				Components					Inspected	
C	omment									
					Estimated			Actual		
#	Material / Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	<b>Unit Cost</b>	Total	
1	Health and Safety	Smoke detector	Each	1						
2	Labor	Labor	Each	1						
(	Other Detail						1			
L										
				Measure Sub Total:			Sub Total:			
	Field Notes:									

	Measure	•	or Barrier Needed ement/CrawIspace)(82	4 sqft)		Componen	ts			Inspected
C	comment	remove (		s filled with debris and personal items. Take approx. 2 hours to and personal items before installing vapor barrier and put back impleted.						
Approx. 824sqft										
Must be 6 mil poly. Must be installed 100% of crawlspace with 12" turned up all walls and support piers. Must be securely fastened. Must be cleated down to earth. Must be secured at all seams. Refer to Attachment A- Standards for Weatherization Materials and Southeast Field Guide.										
					Estimated			Actual		
#	Material /	Labor	Description / Comment	Units	Qty	<b>Unit Cost</b>	Total	Qty	Unit Cost	Total
1	Health a	nd Safety	Basement / crawlspace vapor barrier	SqFt	824					
2	Labor		Labor	SqFt	824					
(	Other Detai	7			1	1		1		
L										
					Measure Sub Total:			Sub Total:		
	Field Note	es:								
				Work O	rder Gra	and Total:		Gran	d Total:	